

Summary of Fire Compliance Works to be carried out in the MNB in March and April 2022

Apartment Number	What Work is Required	Who is responsible	Status
602	Requires a smoke alarm to be installed. Door is binding on carpet preventing auto closure	Lot Owner Lot Owner	Pending
603	Requires a smoke alarm to be installed.	Lot Owner	Pending
604	Requires a LED indicator type thermal detector	Owners Corporation	Pending
607	Requires a LED indicator type thermal detector	Owners Corporation	Pending
610	Requires a smoke alarm to be installed.	Lot Owner	Pending
611	Requires a LED indicator type thermal detector Door may require planing	Owners Corporation Owners Corporation	Pending
613	Requires a LED indicator type thermal detector	Owners Corporation	Pending
614	Requires a LED indicator type thermal detector	Owners Corporation	Pending
615	Requires a smoke alarm to be installed. Non-compliant door hardware to be removed	Lot Owner Lot Owner	Pending
616	Requires a LED indicator type thermal detector	Owners Corporation	Pending
617	Requires a LED indicator type thermal detector	Owners Corporation	Pending
618	Requires a LED indicator type thermal detector	Owners Corporation	Pending
619	Requires a LED indicator type thermal detector	Owners Corporation	Pending
620	Requires a LED indicator type thermal detector	Owners Corporation	Pending
635	Requires a smoke alarm to be installed.	Lot Owner	Pending
640	Requires a smoke alarm to be installed.	Lot Owner	Pending
703	Door may require adjusting Requires a smoke alarm to be installed.	Owners Corporation Lot Owner	Pending
706	Door closer to be reinstalled	Owners Corporation	Pending
707	Requires a smoke alarm to be installed.	Lot Owner	Pending
708	Door closer to be replaced Requires a smoke alarm to be installed.	Owners Corporation Lot Owner	Pending
709	Requires a smoke alarm to be installed.	Lot Owner	Pending
712	Requires a smoke alarm to be installed.	Lot Owner	Pending
713	Requires a smoke alarm to be installed.	Lot Owner	Pending
717	Requires a smoke alarm to be installed.	Lot Owner	Pending
718	Door closer is missing and must be replaced Requires a smoke alarm to be installed. Non-compliant door hardware to be removed	Lot Owner Lot Owner Lot Owner	Pending
721	Requires a smoke alarm to be installed. Non-compliant door hardware to be removed	Lot Owner Lot Owner	Pending
723	Door closer to be adjusted		Pending
726	Requires a smoke alarm to be installed.	Lot Owner	Pending
727	Requires a smoke alarm to be installed.	Lot Owner	Pending
728	Requires a smoke alarm to be installed.	Lot Owner	Pending
729	Requires a smoke alarm to be installed.	Lot Owner	Pending
730	Door is binding on carpet preventing auto closure	Lot Owner	Pending
731	Requires new battery for smoke alarm	Lot Owner	Pending
735	Door closer to be adjusted		Pending
736	Requires a smoke alarm to be installed.	Lot Owner	Pending
733	Requires a LED indicator type thermal detector	Owners Corporation	Pending
738	Requires a smoke alarm to be installed.	Lot Owner	Pending
740	Requires a smoke alarm to be installed.	Lot Owner	Pending
801	Requires a LED indicator type thermal detector Door closer to be adjusted or replaced	Owners Corporation	Pending
802	Requires a LED indicator type thermal detector Requires a smoke alarm to be installed	Owners Corporation Lot Owner	Pending
803	Requires a LED indicator type thermal detector Non-compliant door hardware to be removed	Owners Corporation Lot Owner	Pending
804	Requires a LED indicator type thermal detector	Owners Corporation	Pending
805	Requires a LED indicator type thermal detector	Owners Corporation	Pending
806	Requires a LED indicator type thermal detector	Owners Corporation	Pending
807	Requires a LED indicator type thermal detector Requires a smoke alarm to be installed	Owners Corporation Lot Owner	Pending
808	Requires a LED indicator type thermal detector	Owners Corporation	Pending

Summary of Fire Compliance Works to be carried out in the MNB in March and April 2022

Apartment Number	What Work is Required	Who is responsible	Status
	Requires a smoke alarm to be installed	Lot Owner	
809	Requires a LED indicator type thermal detector	Owners Corporation	Pending
810	Requires a LED indicator type thermal detector	Owners Corporation	Pending
811	Requires a smoke alarm to be installed Door closer to be adjusted or replaced	Lot Owner	Pending
813	Requires a LED indicator type thermal detector Requires a smoke alarm to be installed	Owners Corporation Lot Owner	Pending
814	Requires a smoke alarm to be installed	Lot Owner	Pending
817	Requires a smoke alarm to be installed	Lot Owner	Pending
818	Requires a LED indicator type thermal detector Door closer to be adjusted or replaced	Owners Corporation	Pending
820	Requires a LED indicator type thermal detector Door closer to be adjusted or replaced	Owners Corporation	Pending
823	Requires a LED indicator type thermal detector Door closer to be adjusted or replaced	Owners Corporation	Pending
824	Requires a LED indicator type thermal detector	Owners Corporation	Pending
825	Requires a LED indicator type thermal detector Door closer to be adjusted or replaced	Owners Corporation	Pending
828	Requires a LED indicator type thermal detector	Owners Corporation	Pending
829	Requires a smoke alarm to be installed	Lot Owner	Pending
830	Requires a smoke alarm to be installed	Lot Owner	Pending
832	Requires a smoke alarm to be installed	Lot Owner	Pending
833	Requires 2 LED indicator type thermal detector	Owners Corporation	Pending
834	Requires a LED indicator type thermal detector	Owners Corporation	Pending
835	Requires a LED indicator type thermal detector	Owners Corporation	Pending
836	Requires a LED indicator type thermal detector	Owners Corporation	Pending
837	Door closer to be adjusted or replaced		Pending
838	Requires a LED indicator type thermal detector	Owners Corporation	Pending
840	Requires a LED indicator type thermal detector	Owners Corporation	Pending
901	Requires a LED indicator type thermal detector Requires a smoke alarm to be installed	Owners Corporation	Pending
902	Requires a LED indicator type thermal detector	Owners Corporation	Pending
903	Requires a LED indicator type thermal detector	Owners Corporation	Pending
904	Door closer to be adjusted or replaced	Owners Corporation	Pending
905	Requires a smoke alarm to be installed Door closer to be adjusted or replaced	Owners Corporation Owners Corporation	Pending
906	Requires a LED indicator type thermal detector	Owners Corporation	Pending
907	Requires a LED indicator type thermal detector Check to see that all thermal detectors have been installed correctly after renovation	Owners Corporation Lot Owner	Pending
908	Requires a LED indicator type thermal detector	Owners Corporation	Pending
909	Requires a LED indicator type thermal detector	Owners Corporation	Pending
910	Requires a smoke alarm to be installed	Lot Owner	Pending
911	Requires a LED indicator type thermal detector	Owners Corporation	Pending
912	Requires a LED indicator type thermal detector Requires a smoke alarm to be installed	Owners Corporation Lot Owner	Pending
914	Requires a LED indicator type thermal detector	Owners Corporation	Pending
915	Requires a LED indicator type thermal detector Requires a smoke alarm to be installed	Owners Corporation Lot Owner	Pending
916	Requires a LED indicator type thermal detector	Owners Corporation	Pending
919	Requires a LED indicator type thermal detector Requires a smoke alarm to be installed	Owners Corporation Lot Owner	Pending
920	Requires a smoke alarm to be installed Door closer to be adjusted or replaced	Lot Owner	Pending
925	Requires a smoke alarm to be installed	Lot Owner	Pending
927	Non-compliant door hardware to be removed	Lot Owner	Pending
929	Door is not latching properly	Lot Owner	Pending
931	Requires a LED indicator type thermal detector	Owners Corporation	Pending
932	Requires a LED indicator type thermal detector Door closer requires adjusting	Owners Corporation	Pending

Summary of Fire Compliance Works to be carried out in the MNB in March and April 2022

Apartment Number	What Work is Required	Who is responsible	Status
933	Requires a smoke alarm to be installed	Lot Owner	Pending
937	Requires a LED indicator type thermal detector	Owners Corporation	Pending
938	Requires a smoke alarm to be installed	Lot Owner	Pending
939	Requires a LED indicator type thermal detector	Owners Corporation	Pending
940	Requires a LED indicator type thermal detector Requires a smoke alarm to be installed Door is not latching correctly Non-compliant door hardware to be removed	Owners Corporation Lot Owner Owners Corporation Lot Owner	Pending